

# Airport Renovations & New Construction Projects



Port Isabel - Cameron County Airport  
Port Isabel, Texas




New Roof Completed Spring 2009



Aerial View of airport runways



EXISTING RUNWAY  
*over - grown grass and cracks*





High power washer used to remove debris from cracks . . .



Worker preps runway cracks for sealant



Deteriorated concrete edges and joints



a Jet fuel resistant silicon joint sealant is applied to repair cracks, corners and prevent weed growth on runway





Finished surface . . .

# Trenching for electrical runway signage




Newly installed runway lighting



# Electrical casings for runway signage







Electrical canisters buried underground for new directional signage on taxiways



New signage identifying main runway



By: Lansford Construction  
Lampasas, TX

with LANSFORD  
**ERECTOR TUBE**  
CORPORATION  
100 W. 10th St. - Suite 200 - Lampasas, TX 76786-0200  
PH: 817-437-6000 or 800-821-5278 Fax: 817-437-4000

T- Hangars to be built on site




Location Site for T-Hangars



Concrete removal for T- Hangar site



T-Hangar site prep work



Construction of New Terminal  
to begin  
Spring of 2010 . . .