

Airport Runway Renovations & New Construction Projects



**Port Isabel - Cameron County Airport
Port Isabel, Texas**

Aerial View



Hurricane Dolly 2008





New Roof Completed Spring 2009



EXISTING RUNWAY

over - grown grass and cracks



High power washer used to remove debris from cracks . . .



Deteriorated concrete edges and joints



**a Jet fuel resistant
silicon joint sealant is
applied to repair
cracks and prevent
weed growth on
runway**



Finished surface . . .

Trenching for NEW electrical runway signage



Newly installed runway lighting



“NEW” Electrical casings for runway signage





Electrical canisters buried underground for new directional signage on taxiways



D 13-31

New signage identifying main runway



New T-Hanger Facility *Completed* 2010





New Airport Terminal Building

**Completed
2011**

